



## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2022-0873; Project Identifier MCAI-2022-00060-T]

RIN 2120-AA64

#### Airworthiness Directives; Embraer S.A. Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Embraer S.A. Model EMB-545 and EMB-550 airplanes. This proposed AD was prompted by a report that there is a possibility of the shoulder belt getting stuck during flight due to a step between the divan shroud chamfer and the sideledge panel. This proposed AD would require installing, on the right- and left-hand side divan, a protective fairing covering on the divan shroud and the sideledge panel, as specified in an Agência Nacional de Aviação Civil (ANAC) AD, which is proposed for incorporation by reference. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- Fax: 202-493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West

Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For material that will be incorporated by reference (IBR) in this AD, contact National Civil Aviation Agency (ANAC), Aeronautical Products Certification Branch (GGCP), Rua Dr. Orlando Feirabend Filho, 230 – Centro Empresarial Aquarius – Torre B – Andares 14 a 18, Parque Residencial Aquarius, CEP 12.246-190 – São José dos Campos – SP, Brazil; telephone 55 (12) 3203-6600; email [pac@anac.gov.br](mailto:pac@anac.gov.br); Internet [www.anac.gov.br/en/](http://www.anac.gov.br/en/). You may find this material on the ANAC website at <https://sistemas.anac.gov.br/certificacao/DA/DAE.asp>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0873.

### **Examining the AD Docket**

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0873; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

**FOR FURTHER INFORMATION CONTACT:** Ho-Joon Lim, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3405; email [ho-joon.lim@faa.gov](mailto:ho-joon.lim@faa.gov).

## **SUPPLEMENTARY INFORMATION:**

### **Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under ADDRESSES. Include “Docket No. FAA-2022-0873; Project Identifier MCAI-2022-00060-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

### **Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Ho-Joon Lim, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3405; email

ho-joon.lim@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

## **Background**

ANAC, which is the aviation authority for Brazil, has issued ANAC AD 2021-11-01R1, effective January 21, 2022 (ANAC AD 2021-11-01R1) (also referred to as the MCAI), to correct an unsafe condition for certain Embraer S.A. Model EMB-545 and EMB-550 airplanes.

This proposed AD was prompted by a report that there is a possibility of the shoulder belt getting stuck during flight due to a step between the divan shroud chamfer and the sideledge panel. This set up may interfere with the correct kinematics of the shoulder belt during its retraction. The FAA is proposing this AD to address the possibility of a stuck shoulder belt during flight, which could affect the shoulder belt release during turbulence or an emergency landing situation and result in injury to passengers and the flightcrew. See the MCAI for additional background information.

## **Related Service Information Under 1 CFR Part 51**

ANAC AD 2021-11-01R1 specifies procedures for installing, on the right- and left-hand side divan, a protective fairing covering on the divan shroud and the sideledge panel. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

## **FAA's Determination**

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after

determining that the unsafe condition described previously is likely to exist or develop in other products of these same type designs.

### **Proposed AD Requirements in this NPRM**

This proposed AD would require accomplishing the actions specified in ANAC AD 2021-11-01R1 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

### **Explanation of Required Compliance Information**

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate ANAC AD 2021-11-01R1 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with ANAC AD 2021-11-01R1 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Service information required by ANAC AD 2021-11-01R1 for compliance will be available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0873 after the FAA final rule is published.

### **Costs of Compliance**

The FAA estimates that this proposed AD would affect 63 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

#### **Estimated costs for required actions**

<b>Labor cost</b>	<b>Parts cost</b>	<b>Cost per product</b>	<b>Cost on U.S. operators</b>
Up to 14 work-hours X \$85 per hour = Up to \$1,190	\$400	Up to \$1,590	Up to \$100,170

According to the manufacturer, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected operators. The FAA does not control warranty coverage for affected operators. As a result, the FAA has included all known costs in the cost estimate.

### **Authority for this Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### **Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39 - AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**Embraer S.A.:** Docket No. FAA-2022-0873; Project Identifier MCAI-2022-00060-T.

**(a) Comments Due Date**

The FAA must receive comments on this airworthiness directive (AD) by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Embraer S.A. Model EMB-545 and EMB-550 airplanes, certificated in any category, as identified in paragraph (a)(2) of Agência Nacional de Aviação Civil (ANAC) AD 2021-11-01R1, effective January 21, 2022 (ANAC AD 2021-11-01R1).

**(d) Subject**

Air Transport Association (ATA) of America Code 25, Equipment/furnishings.

**(e) Unsafe Condition**

This AD was prompted by a report that there is a possibility of the shoulder belt getting stuck during flight due to a step between the divan shroud chamfer and the sideledge panel. This set up may interfere with the correct kinematics of the shoulder belt during its retraction. The FAA is issuing this AD to address the possibility of a stuck shoulder belt during flight, which could affect the shoulder belt release during turbulence or an emergency landing situation and result in injury to passengers and the flightcrew.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, ANAC AD 2021-11-01R1.

**(h) Exceptions to ANAC AD 2021-11-01R1**

(1) Where ANAC AD 2021-11-01R1 refers to its effective date, this AD requires using the effective date of this AD.

(2) The requirements specified in paragraph (b)(1) of ANAC AD 2021-11-01R1 do not apply to this AD.

(3) Where paragraph (b)(2) of ANAC AD 2021-11-01R1 specifies that it applies to certain airplanes, replace the text “airplanes identified in paragraph (a)(2) of this [ANAC] AD, and which are not listed in the paragraph (a)(1) of this [ANAC] AD,” with “airplanes identified in paragraph (a)(2) of this [ANAC] AD.”

(4) The “Alternative method of compliance (AMOC)” section of ANAC AD 2021-11-01R1 does not apply to this AD.

**(i) Additional AD Provisions**

The following provisions also apply to this AD:



(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or ANAC; or ANAC's authorized Designee. If approved by the ANAC Designee, the approval must include the Designee's authorized signature.

**(j) Related Information**

(1) For ANAC AD 2021-11-01R1, contact National Civil Aviation Agency (ANAC), Aeronautical Products Certification Branch (GGCP), Rua Dr. Orlando Feirabend Filho, 230 – Centro Empresarial Aquarius – Torre B – Andares 14 a 18, Parque Residencial Aquarius, CEP 12.246-190 – São José dos Campos – SP, Brazil; telephone 55 (12) 3203-6600; email [pac@anac.gov.br](mailto:pac@anac.gov.br); Internet [www.anac.gov.br/en/](http://www.anac.gov.br/en/). You may find this ANAC AD on the ANAC website at <https://sistemas.anac.gov.br/certificacao/DA/DAE.asp>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call

206-231-3195. This material may be found in the AD docket at

<https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0873.

(2) For more information about this AD, contact Ho-Joon Lim, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3405; email [ho-joon.lim@faa.gov](mailto:ho-joon.lim@faa.gov).

Issued on July 7, 2022.

Christina Underwood, Acting Director,  
Compliance & Airworthiness Division,  
Aircraft Certification Service.

[FR Doc. 2022-14867 Filed: 7/12/2022 8:45 am; Publication Date: 7/13/2022]